




**Issue C**



**NOTE!**

Mk.3 Replacement Burners for appliances before Serial No. 45\*\*\*\*1562 require bracket to align control box with re-set hole.



Item	Part No.	Description	Ex.Vat.	Inc.Vat.	Item	Part No.	Description	Ex.Vat.	Inc.Vat.
3*	008/KV355	Door Seal Set Inc. Adhesive .....	30.00	36.00	31#	005/KV06	Lower Hood Panel .....	152.00	182.40
4	006/KV18	Glass (Inc Seal) .....	75.00	90.00	32#	005/KV09	Top Hood Panel .....	140.00	168.00
5*	008/TV95	Glass Seal (Neoprene) .....	20.00	24.00	33#	005/TV16	Bottom Panel .....	79.00	94.80
6	004/KV23	Glass Retainer .....	0.70	0.84	34	008/TV11	Flame Effect Cartridge .....	NA	
7	002/TV07	Front Firebar .....	59.50	71.40	35	008/TV15	Oil Burner .....	745.00	894.00
8	008/KV16	R.H. Door Handle .....	22.00	26.40	36	001/TV10B	Firebox/Boiler (OLX)		
9	002/KV14	Door Catch Cam .....	10.20	12.24	37	004/KV50	Panel Fixing Bracket .....	2.35	2.82
10	008/KV13	L.H. Door Knob .....	3.55	4.26	38	004/TV03	Access Door .....	36.50	43.80
11	008/TV19	Thermostat Knob .....	4.65	5.58	39	004/TV25	Thermostat Mounting Box .....	NA	
12	008/TV20	Flame Effect Knob .....	2.95	3.54	40	004/TV33	Thermostat Phial Clamping Plate .....	5.85	7.02
13	008/BW39/S	Hinge Pin Set .....	3.80	4.56	41	008/TV17	Inner Front Insulation .....	NA	
14	008/TV80	Fluorescent Lamp .....	8.90	10.68	42	010/TV14	Inner Front Plate		
15	008/TV78	Amber Lamp Sleeve .....	3.55	4.26	43	010/TV43	Inner Front Plate Fixing Bracket		
16	040/TV69	Reset Button Extension .....	2.60	3.12	44	008/TV86	Air Inlet Gasket .....	2.60	3.12
17	008/TV09	Access Door Insulation .....	24.00	28.80	45	008/TV49	Air Inlet Manifold .....	8.50	10.20
18	008/TV22	Thermostat .....	NA		46	010/TV84/1	Air Inlet Side Cover		
19	008/TV24	Flame Effect Rotary Switch .....	3.30	3.96	47a	010/TV108	Air Control - Location Disk		
20	008/TV27	Hinge Post .....	7.90	9.48	47b	010/TV109	Air Control - Pointer		
21a	011/TV106	Blast Chamber Insulation Board Set .....	41.50	49.80	47c	010/TV110	Air Control - Adjuster		
23a	010/TV31	Baffle -No.1 .....	35.00	42.00	48	010/TV42S	Flue Fixing Bracket (Set of 3) .....	15.40	18.48
24a	010/TV47A	Baffle -No.2. ....	33.00	39.60	49	011/PV27	Back Ceramic Gasket .....	13.90	16.68
24b	010/TV47B	Baffle No.3 .....	33.00	39.60	50	040/TV77	Service Valve & Elbow .....	24.00	28.80
25a	010/TV48A	Baffle - No.4 .....	23.50	28.20	51	040/TV94	Burner Mounting Flange		
26	008/TV13	Fibreglass Coal Effect .....	35.00	42.00	52		M12 Half Nuts		
27#	003/TV01	L.H. Door .....	126.00	151.20	53#	005/TV06	Lower Top Panel - For Fan Heater .....	144.00	172.80
28#	003/TV02	R.H. Door .....	126.00	151.20	54	008/TV111	Fan Heater .....	NA	
29#	005/TV04	L.H. Side Panel .....	102.00	122.40	55	010/TV137	Control Box Offset Bracket .....	7.90	9.48
30#	005/TV05	R.H. Side Panel .....	102.00	122.40					

\* These items are not shown on the drawing.  
 ## Please specify colour when ordering Prices are shown in pounds sterling with vat at 20% They are correct at the date shown but may be subject to change without notice. E. & O.E These prices are subject to a carriage charge.

To obtain spare parts please contact your local stockist giving Model, Part No. and Description. In case of difficulty contact the manufacturer at the address shown. This drawing is for identification purposes only.

